Quadrathane[™] ALC-93A-B20

Thermoplastic Polyurethane Elastomer (PC Based)

Biomerics, LLC

Message:

Quadrathane™ ALC-93A-B20 is high performance aliphatic polycarbonate thermoplastic polyurethane. The polymer is loaded with 20% barium sulfate by weight, is naturally white, and supplied in small pellets for ease of processing. The material exhibits excellent mechanical properties, oxidative stability, biocompatibility, superior biostability in long term implantable devices, chemical resistance, non-yellowing during aging and softening at body temperature. The resin has consistent melt flow properties making it ideal for extrusion.

Quadrathane™, Quadraflex™, Quadraban™ and Quadraplast™ performance polymers are primarily used in life science and medical applications including vascular access devices, surgical supplies, respiratory devices, tracheotomy devices, and other medical applications. Typical end products include tubing, catheter parts, balloons, and various medical device components. These performance polymers are available in a variety of durometers, radiopacifiers, colors, and custom formulations.

General Information					
Filler / Reinforcement	Barium sulfate, 20% filler by weight				
Features	Antioxidation				
	Workability, good				
	Good liquidity				
	Good color stability				
	Good chemical resistance				
	Biocompatibility				
	aliphatic				
	Resistance				
Uses	Pipe fittings				
	Human implant				
	Surgical instruments				
	Medical/nursing supplies				
Appearance	White				
Forms	Particle				
Processing Method	Extrusion				
	Injection molding				
Physical	Nominal Value	Unit	Test Method		
Specific Gravity	1.35	g/cm³	ASTM D792		
Melt Mass-Flow Rate (MFR) (190°C/2.16					
kg)	7.5	g/10 min	ASTM D1238		
Molding Shrinkage - Flow	0.60 - 1.0	%	ASTM D955		
Hardness	Nominal Value	Unit	Test Method		
Durometer Hardness (Shore A)	93		ASTM D2240		
Mechanical	Nominal Value	Unit	Test Method		
Flexural Modulus	48.3	MPa	ASTM D790		

Tensile StressASTM P412100% strain11.7MPaASTM D412200% strain26.2MPaASTM D412Tensile Strength (Break)44.8MPaASTM D412Tensile Strength (Break)430%ASTM D412Tensile Strength (Break)430%ASTM D412Tensile Strength (Break)400hrPost Cure Time (38'C)54.4'CDrying Temperature54.4'CDrying Temperature40.0hrSuggested Max Moisture< 30.5-3%Stozze Temperature191'CNozze Temperature196'CNozze Temperature204'CNozze Temperature210-3.51.0'CStrew Compression Ratio2.51.0'CTensite Strew Compression Ratio2.51.0'CDrying Time4.44-32.2'C'CNozze TemperatureJandal Bast Strew Gryde (2016 Gryde) Hickness)Strew Compression Ratio2.51.0'CStrew Compression Ratio4.44'CDrying TemperatureJandal Bast Strew Gryde (2016 Gryde) Hickness)Drying Temperature4.64'CDrying TemperatureJandal Bast Strew Gryde (2016 Gryde) Hickness'Drying Temperature4.64'CDrying Temperature4.64'C <th>Elastomers</th> <th>Nominal Value</th> <th>Unit</th> <th>Test Method</th>	Elastomers	Nominal Value	Unit	Test Method
10% strain11.7MPaASTM D41230% strain26.2MPaASTM D412Tensile Strength (Break)44.8MPaASTM D412Tensile Elongation (Break)430%ASTM D412Tensile Elongation (Break)6.0 - 10hr	Tensile Stress (10% Strain)	6.89	MPa	ASTM D412
30% strain26.2MPaASTM D412Tensile Strength (Break)44.9MPaASTM D412Tensile Elongation (Break)430%ASTM D412TensosetNominal ValueUnitPost Cure Time (38°C)6.0 - 10hrDrying Timeperature54.4°CDrying Timeperature4.0%Suggested Max Moisture4.0%Store Timeperature191°CNotzel Temperature196°CNozel Temperature196°CNozel Temperature196°CNozel Temperature196°CNozel Temperature196°CNozel Temperature196°CNozel Temperature196°CProcessing (Mell Temp204°CMold Temperature196°CStrew Compression Ratio2100°CStrew Compression Ratio2100°CDrying Temperature444-32.2°CDrying Temperature4104°CDrying Temperature4104°CDrying Temperature4104°CDrying Temperature40.0%Drying Temperature40.0%Drying Temperature40.0%Suggested Max Moisture40.0%Cylinder Zone Temp.188°C	Tensile Stress			ASTM D412
Tensile Elongation (Break)448MPaASTM D412Tensile Elongation (Break)Nominal ValueUnitPost Cure Time (B8*C)6.0 - 10hrInjectionNominal ValueUnitDying Temperature54.4*CDying Timperature4.0hrSuggested Max Moisture<3.0E-3	100% strain	11.7	MPa	ASTM D412
Tensile Elongation (Break)430%ASTM D412ThermosetNominal ValueInitPost Cure Time (38*C)6.0 - 10hrInjectionNominal ValueUnitDrying Temperature54.4*CSuggested Max Moisture< 3.0E-3	300% strain	26.2	MPa	ASTM D412
norma Nominal Value Unit Post Cure Time (38°C) 6.0 - 10 hr Injection Nominal Value Unit Drying Temperature 54.4 °C Drying Time 4.0 hr Suggested Max Moisture < 3.0E-3	Tensile Strength (Break)	44.8	MPa	ASTM D412
Post Cure Time (38°C)60-10hrInjectionNominal ValueUnitDrying Temperature54.4°CDrying Time4.0hrSuggested Max Moisture< 3.0E-3	Tensile Elongation (Break)	430	%	ASTM D412
InjectionNominal ValueUnitDrying Temperature54.4"CDrying Time4.0InSuggested Max Moisture<30E-3	Thermoset	Nominal Value	Unit	
Joying Temperature 54.4 "C Drying Time 4.0 hr Drying Time 4.0 hr Suggested Max Moisture < 3.0E-3	Post Cure Time (38°C)	6.0 - 10	hr	
Dying Time 4.0 hr Dying Time 4.0 hr Suggested Max Moisture 3.0E-3 % Rear Temperature 177 °C Front Temperature 191 °C Nozzle Temperature 196 °C Nozzle Temperature 196 °C Processing (Melt) Temp 204 °C Mold Temperature 4.44 - 32.2 °C Mold Temperature 510w °C Screw Compression Ratio 2.5:1.0 - 3.5:1.0 Injection instructions Vortion State Vortion State Extrusion Nominal Value Unit Drying Time 4.4 °C Drying Time 4.0 rC Suggested Max Moisture <0.030	Injection	Nominal Value	Unit	
Suggested Max Moisture< 3.0E-3%Rear Temperature177CRoot Temperature191CNozzle Temperature196CNozzle Temperature204CMold Temperature4.44 - 32.2CInjection RateSlow-Screw Compression Ratio2.5:1.0 - 3.5:1.0Injection Instructions-ExtrusionNomin ValueUnitDring Temperature54.4*CNong Stagested Max Moisture6.030%Suggested Max Moisture171*CCylinder Zone 1 Temp.188.4*CCylinder Zone 2 Temp.188.4*CCylinder Zone 3 Temp.193.4*CCylinder Zone 4 Temp.193.4*CDie Temperature193.4*CDie Temperature193.4*CSter Sone 3 Temp.6.39.12.4*CMath Temperature193.4*CSter Sone 3 Temp.193.4*CSter Sone 3 Temp.193.4 </td <td>Drying Temperature</td> <td>54.4</td> <td>°C</td> <td></td>	Drying Temperature	54.4	°C	
Norm Norm Rear Temperature 177 °C Prone Temperature 191 °C Nozzle Temperature 196 °C Processing (Melt) Temp 204 °C Mold Temperature 444 - 32.2 °C Injection Rate Slow - Screw Compression Ratio 2.51.0 - 3.51.0 - Injection instructions 2.51.0 - 3.51.0 - Injection Instructions Sow - Injection Instructions 5.51.0 - 3.51.0 - Injection Instructions - - Injection Instructions - - Injection Speed: 10 g/secCooling/Hold Time: Jast S0% of cycle (20 to 60 - Sectiong on thickness) - Extrusion Nominal Value Unit Drying Temperature 54.4 °C Suggested Max Moisture <0.030	Drying Time	4.0	hr	
Front Temperature191"CNozzle Temperature196"CNozzle Temperature204"CMold Temperature4.44 - 32.2"CInjection RateSow-Screw Compression Ratio2.51.0 - 3.51.0Injection Instructions2.51.0 - 3.51.0Injection Instructions-Injection Speed: 10 g/secCooling/Hold TIme: Jast 50% of cycle (20 to 60 - Section of thickness)ExtrusionNominal ValueUnitDying Temperature54.4"CDying Temperature4.0"CSuggested Max Moisture0.030%Cylinder Zone 1 Temp.182"CCylinder Zone 1 Temp.193"CQuinder Zone 4 Temp.193"CMel Temperature193"CDifferengerature193 - 216"CDifferengerature689 - 124MPa	Suggested Max Moisture	< 3.0E-3	%	
Nozzle Temperature196°CNozzle Temperature204°CMold Temperature4.44 - 32.2°CInjection RateSlowScrew Compression Ratio2.5:1.0 - 3.5:1.0Injection instructionsInjection Speed: 10 g/secCooling/Hold Time, at least 50% of cycle (20 to 60 second) and thickness)ExtrusionNominal ValueUnitDrying Temperature54.4°CDrying Time4.0rCSuggested Max Moisture60.030%Cylinder Zone 1 Temp.17.1°CCylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CDie Temperature193 - 216°CDie Temperature193 - 216°CBack Pressure689 - 12.4MPa	Rear Temperature	177	°C	
Processing (Melt) Temp204°CMold Temperature4.44 - 32.2°CInjection RateSlow·CScrew Compression Ratio2.5.1.0 - 3.5.1.0·CInjection instructionsScrew Cooling/Hold Timer Soft order (20 to 60 - Secting)·CInjection Speed: 10 g/secCooling/Hold Timer Soft order (20 to 60 - Secting)·CExtusionNominal ValueUnitDrying Time6.4.4°CSuggested Max Moisture6.0.30%CCylinder Zone 1 Temp.182°CCylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CDif Temperature193 - 216°CDie Temperature6.9 - 12.4MPa	Front Temperature	191	°C	
Mold Temperature 4.44 - 32.2 °C Injection Rate Slow	Nozzle Temperature	196	°C	
Injection Rate Slow Screw Compression Ratio 2.5:1.0 - 3.5:1.0 Injection instructions Injection Species 10 g/secCooling/Hold TIWE states 50% of cycle (20 to 60 - Section 4 and 10	Processing (Melt) Temp	204	°C	
Screw Compression Ratio 2.51.0 - 3.5:1.0 Injection instructions Injection Speed: 10 g/secCooling/Hold Time: Long, at least 50% of cycle (20 to 60 sected) on thickness) Extrusion Nominal Value Unit Drying Temperature 54.4 °C Drying Time 4.0 hr Suggested Max Moisture < 0.030	Mold Temperature	4.44 - 32.2	°C	
Injection instructions Injection Speed: 10 g/secCooling/Hold TIme: Long, at least 50% of cycle (20 to 60 sectopending on thickness) Extrusion Nominal Value Unit Drying Temperature 54.4 °C Drying Time 4.0 hr Suggested Max Moisture < 0.030	Injection Rate	Slow		
Injection Speed: 10 g/secCooling/Hold Time; at least 50% of cycle (20 to 60 section on thickness) Extrusion Nominal Value Unit Drying Temperature 54.4 °C Drying Time 4.0 hr Suggested Max Moisture <0.030	Screw Compression Ratio	2.5:1.0 - 3.5:1.0		
ExtrusionNominal ValueUnitDrying Temperature54.4°CDrying Time4.0hrSuggested Max Moisture< 0.030	Injection instructions			
Drying Temperature54.4°CDrying Time4.0hrSuggested Max Moisture< 0.030	Injection Speed: 10 g/secCooling/Ho	old TIme: Long, at least 50% of cycle (20 to 60 secs depending on thic	kness)
Drying Time4.0hrSuggested Max Moisture< 0.030	Extrusion	Nominal Value	Unit	
Suggested Max Moisture< 0.030%Cylinder Zone 1 Temp.171°CCylinder Zone 2 Temp.182°CCylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CMelt Temperature193°CDie Temperature193 - 216°CBack Pressure6.89 - 12.4MPa	Drying Temperature	54.4	°C	
Cylinder Zone 1 Temp.171°CCylinder Zone 2 Temp.182°CCylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CMelt Temperature193°CDie Temperature193 - 216°CBack Pressure6.89 - 12.4MPa	Drying Time	4.0	hr	
Cylinder Zone 2 Temp.182°CCylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CMelt Temperature193°CDie Temperature193 - 216°CBack Pressure6.89 - 12.4MPa	Suggested Max Moisture	< 0.030	%	
Cylinder Zone 3 Temp.188°CCylinder Zone 4 Temp.193°CMelt Temperature193°CDie Temperature193 - 216°CBack Pressure6.89 - 12.4MPa	Cylinder Zone 1 Temp.	171	°C	
Cylinder Zone 4 Temp.193°CMelt Temperature193°CDie Temperature193 - 216°CBack Pressure6.89 - 12.4MPa	Cylinder Zone 2 Temp.	182	°C	
Melt Temperature 193 °C Die Temperature 193 - 216 °C Back Pressure 6.89 - 12.4 MPa	Cylinder Zone 3 Temp.	188	°C	
Die Temperature 193 - 216 °C Back Pressure 6.89 - 12.4 MPa	Cylinder Zone 4 Temp.	193	°C	
Back Pressure 6.89 - 12.4 MPa	Melt Temperature	193	°C	
	Die Temperature	193 - 216	°C	
Extrusion instructions	Back Pressure	6.89 - 12.4	MPa	
	Extrusion instructions			

Screen Pack: 250 meshScrew Speed: Low sheer, 150 to 250 rpmWater Bath: 80 to 110°F

The information and data on this page are provided by manufacturers and document providers. SHANGHAI SUSHENG assumes no legal liability. It is strongly recommended to verify all technical data with material suppliers before final material selection. All rights belong to the original authors. If any infringement occurs, please contact us immediately.

Recommended distributors for this material

Susheng Import & Export Trading Co.,Ltd.

Tel: +86 21 5895 8519

Phone: +86 13424755533

Email: sales@su-jiao.com

No. 215, Lianhe North Road, Fengxian District, Shanghai, China

